

Product Change Notification

PCN No: 2025-CRP-02

Date of Notification: November 5th, 2024

Notification Type: Process Change

Products Impacted: HG85-0015, HG85-0014, HG85-0016, HG85-021

Dear Valued Customer,

Smiths has detected a risk whereby the ZHG085-005 (85 POS PLUG INSULATOR) may become damaged, during assembly or field use, in a way that causes loss of proper pin retention. Smiths sub tier supplier(s) may begin applying 3M DP-125 EPOXY to the back of the insulator after pin installation to strengthen pin retention and mitigate impact of this damage

Best regards,

Daniel Ratzlaff

Business Manager, Medical J&J

Connectors BU

daniel.ratzlaff@smithsinterconnect.com



US Headquarters:

8851 SW Old Kansas Ave.
Stuart, FL USA 34997

UK Headquarters:

4th Floor 11-12, St. James's Square
London, UK SW1Y 4LB



+1 772 286 9300

+44 20 7004 1600



smithsinterconnect.com
info@emc-rflabs.com

info.uk@smithsconnectors.com