

Product Change Notification

PCN No: 2021-PCB-09

Date of Notification: July 16, 2021

Notification Type: Product Obsolescence

Products Impacted: Select Legacy Smiths Interconnect PCB Connectors

Part Numbers Affected: (see list on next page)

Dear Valued Customer,

Due to declining customer requirements over the past few years and the status of the mold tooling required to manufacture the insulators used in these connectors, effective immediately, the following part numbers have been obsoleted, with no possibility for a last time buy.

As a substitute, if warranted, we could research the possibility of a one-time buy for these connectors with machined insulators (may require material and/or specification changes) at a higher price to cover the additional cost. Please respond by August 15, 2021 if you'd be interested in pursuing this alternative.

Best regards,

Tom Kannally
Product Line Manager, PCB Connectors
tom.kannally@smithsinterconnect.com



US Headquarters:
8851 SW Old Kansas Ave.
Stuart, FL USA 34997

UK Headquarters:
4th Floor 11-12, St. James's Square
London, UK SW1Y 4LB



+1 772 286 9300

+44 20 7004 1600



smithsinterconnect.com
info@emc-rflabs.com

info.uk@smithsconnectors.com

C173 series

C173 12FRT/20251
C173 12MCT/20250
C173 29FRT/20253

C174 series

C174081EFNH/20279
C174081EFWH/23224

CID series

CID23254BFCT
CID23254BFDT
CID23254BFLT/21520
CID23254BFSH
CID23254BFST
CID23254BMSH
CID23254BMST
CID41254BFAT
CID41254BFCT
CID41254BFDT
CID41254BFFT
CID41254BFSH
CID41254BFST
CID41254BMSH
CID41254BMST
CID47254BMCT
CID473254BMST/16956

CPM series

CPM-A-22/15 F1AT
CPM-A-22/15 M1AT

FCI series

FCI05AT
FCI05DH
FCI05ST
FCI05ST/1 2730
FCI16CT
FCI16CT/1 2730
FCI16DT
FCI16DT/1 2730
FCI16ST
FCI16ST/1 2730
FCIA50805ST
FCIA50810DT
FCIA50810ST
FCIA50810WT
FCIA50816ST

MCI series

MCI05AT+J77J63:J81
MCI05DH
MCI05ST
MCI05ST/1 2729
MCI05WT
MCI16AT
MCI16CT
MCI16CT/1 2729
MCI16ST
MCI16ST/1 2729
MCIA39605CT
MCIA39610CT
MCIA39610SH
MCIA39610ST
MCIA50805ST
MCIA50810CT
MCIA50816CT
MCIB39622AT
MCIB39622ST

Misc:

10001 INSULATOR MCI05 MKD
10002 INSULATOR FCI05 MKD
10005 INSULATOR MCI16 MKD
10006 INSULATOR FCI16 MKD
10023 SUB MCIB39622 MKD
11773 INSULATOR CID41254BF MKF
12165 INSULATOR CID23254BF MKF
12165 INSULATOR CID23254BF MKM
15686 INSULATOR 12 WAYS P3.5 MKD
15687 INSULATOR 12 WAYS P3.5 MKD
16989 INSULATOR RIF3 CID23 NMK
16989 INSULATOR RIF7 CID47 NMK
20067 INSULATOR 8 WAYS P5.08 MKD
20254 INSULATOR 12 WAYS M MKD
20258 INSULATOR 12 WAYS F MKD
20281 INSULATOR 81 WAYS E MKD
23225 INSULATOR 81 WAYS MOD NMK
23864 INSULATOR+81 HC CONTACTS STD
MALE CONNECTOR 68 WAYS HS/22418
PLUG CONNECT. 3WAYS UNDEREQ T/21985
PLUG CONNECTOR 12 WAYS -/24405
PLUG CONNECTOR 12 WAYS-/15606
PLUG CONNECTOR 3 WAYS-/21090
RECEPT CONNECTOR 12 WAYS - /15605
RECEPT CONNECTOR 12 WAYS-/25522
RECEPT CONNECTOR 8 WAYS H/20066



US Headquarters:
8851 SW Old Kansas Ave.
Stuart, FL USA 34997

UK Headquarters:
4th Floor 11-12, St. James's Square
London, UK SW1Y 4LB



+1 772 286 9300

+44 20 7004 1600



smithsinterconnect.com
info@emc-rflabs.com

info.uk@smithsconnectors.com