

## Product Change Notification

**PCN No:** 2022-PCB-03

**Date of Notification:** February 22, 2022

**Notification Type:** Product Obsolescence

**Products Impacted:** HPF119 connectors

**Part Numbers Affected:** Part numbers with HPF119 prefixes

**Examples:** HPF119UFPL0020  
HPF119UMLKP202

Dear Valued Customer,

The mold tooling required to manufacture the insulators used in the 119 position HPF series connectors has reached the end of life and is no longer capable of manufacturing product to the excellent level of quality expected from Smiths Interconnect.

As a result of this, and declining customer requirements, we are obsoleting these HPF119 series connectors. Currently there is a very limited stock of the insulators used in the HFP119's, which is available for a last time buy of these connectors, on a first-come first-served basis.

If there is interest in a last time buy for the HPF119 connectors, please place your order by March 31, 2022. Thank you.

Best regards,  
Tom Kannally  
Product Line Manager, PCB Connectors  
Connectors BU  
[tom.kannally@smithsinterconnect.com](mailto:tom.kannally@smithsinterconnect.com)



**US Headquarters:**  
8851 SW Old Kansas Ave.  
Stuart, FL USA 34997

**UK Headquarters:**  
4<sup>th</sup> Floor 11-12, St. James's Square  
London, UK SW1Y 4LB



+1 772 286 9300

+44 20 7004 1600



[smithsinterconnect.com](http://smithsinterconnect.com)  
[info@emc-rflabs.com](mailto:info@emc-rflabs.com)

[info.uk@smithsconnectors.com](mailto:info.uk@smithsconnectors.com)