

PRODUCT CHANGE NOTICE

PCN Number: 2024-PCS-03 Issue Date: June 10, 2024
PCN Type: Product/Process Change
 Discontinued Product

Part Number(s) Affected: Part numbers with HPD084 Prefix
Examples: HPD084AMLDX020
HPD084AFLJD020
HPD084AFPB0020
HPD084AMLAP020
Description of the Change: End of Life
Reason for the Change:

Dear Valued Customer,

The mold tooling required to manufacture the insulators used in the HPD 84-way connectors has reached the end of life and is no longer capable of manufacturing product to the excellent level of quality expected from Smiths Interconnect. As a result of this, and declining customer requirements, we are obsoleting these connectors. Smiths will no longer support their sale as a finished good. Smiths cannot support a last time buy. However, our 84-way KA series connector may be a viable replacement.

Effective Date: June 10, 2024
Availability of New Samples: Not Applicable
For more information contact:

Kyle Gobble
Product Line Manager
Defense/Space/Aerospace Connectors



Stuart, FL
United States

kyle.gobble@smithsinterconnect.com

M +1 772 285 5970

smithsinterconnect.com

PRODUCT CHANGE NOTICE

Common 84-way HPD vs KA replacement PNs:

HPD part number	KA part number	Comment / KA deviation
HPD084AMLDX020	KA84-127B P B V32 TH	No transverse fixing screw on KA.
HPD084AFLJD020	KA84-127B E B V31 TAH	No transverse fixing screw on KA.
HPD084AFPB0020	KA84-127B E D V31 TAH	KA Terminations shorter.
HPD084AMLAP020	KA84-127B P B 10 TAH	KA has polarized guide.
HPD084UFCL6020	KA84-127B E R 23 TAH	KA insulator is higher overall than HPD.
HPD084UMBKM02X	KA84-127B P C 10 TH	KA Mounting screw is shorter.
HPD084AFPR0000	KA84-127B E D XX TBH	KA Terminations shorter. Hardware not listed. Idents reversed.
HPD084AFPR0020	KA84-127B E D XX TAH	KA Terminations shorter. Hardware not listed.
HPD084UMMV0000	KA84-127B P D V33 TH	KA Terminations longer. Idents reversed.
HPD084AMMV0020	KA84-127B P D V33 TH	KA Terminations longer.