

## Product Change Notification

**PCN No:** 2021-PCB-01

**Date of Notification:** April 13, 2021

**Notification Type:** Product Obsolescence

**Products Impacted:** FCI & KD series connectors with 10 position female insulators

**Part Numbers Affected with prefixes "FCI10" and "KD10/400F"** (including the following):

FCI10CT & FCI10CT/1\_2730  
FCI10DT  
FCI10ST  
KD10/400FCT & KD10/400FCTKFT  
KD10/400FDT & KD10/400FDTKFT  
KD10/400FST & KD10/400FSTKFT

Dear Valued Customer,

The mold tooling required to manufacture the insulators for the subject connectors has reached the end of life and is no longer capable of manufacturing product to the excellent level of quality expected from Smiths Interconnect. As a result of this, and declining customer requirements for this product line, effective immediately, we are obsoleting the part numbers listed above, with no possibility for a last time buy.

As a substitute, we could research the possibility a one-time buy for these connectors with a machined insulator, at a higher price to cover the additional cost, or if your requirements are on-going, we can research the cost of replacement mold tools. Please respond by June 14, 2021 if you'd be interested in pursuing one of these alternatives.

Best regards,

Tom Kannally  
Product Line Manager, PCB Connectors  
[tom.kannally@smithsinterconnect.com](mailto:tom.kannally@smithsinterconnect.com)



**US Headquarters:**  
8851 SW Old Kansas Ave.  
Stuart, FL USA 34997

**UK Headquarters:**  
4<sup>th</sup> Floor 11-12, St. James's Square  
London, UK SW1Y 4LB



+1 772 286 9300

+44 20 7004 1600



[smithsinterconnect.com](http://smithsinterconnect.com)  
[info@emc-rflabs.com](mailto:info@emc-rflabs.com)

[info.uk@smithsconnectors.com](mailto:info.uk@smithsconnectors.com)